



DEPARTMENT OF PUBLIC HEALTH
CITY OF CHICAGO

FORM NO. CDPH.ROW.03 (STREETERVILLE Right-of-Way)

Notice is hereby given that the site you have requested a permit for is recorded with the City of Chicago Department of Public Health (CDPH) as potentially having environmental contamination on the site and adjacent right-of-way. This environmental contamination could present a threat to human health and safety in connection with work performed at the site, or in the adjacent right-of-way, if proper safeguards are not employed.

A file containing detailed information regarding the aforementioned environmental contamination is available for review at CDPH at 333 S. State St., Room 200, Chicago, Illinois 60604 during normal business hours (8:30AM-4:30PM, Monday through Friday). Contact (312) 745-3152 for an appointment. This file must be reviewed and the remainder of this form completed before the permit can be issued if the ground is exposed or excavated. Please note that for some locations, additional health and safety procedures may be required by law.

Please complete the following:

I have reviewed and understand the documents, maintained by CDPH, regarding environmental contamination of the site and adjacent right-of-way. Further, I will ensure that all work at the subject site and adjacent right-of-way, and any monitoring required including but not limited to radiation monitoring, will be performed in a manner that is protective of human health and the environment and in compliance with all applicable local, state, and federal laws, rules, and regulations, especially those pertaining to worker safety and waste management. I will ensure that the results of any radiation monitoring and/or surveying conducted shall be provided to the CDPH and the United States Environmental Protection Agency within two (2) weeks of their completion. If any elevated levels of radioactive material are detected, I will immediately contact the United States Environmental Protection Agency at (800) 424-8802.

Applicant Name (print): Tim KAWANAGH

Signature: [Signature]

Site Address and Work Location (Describe exact site location and attach map): 4100 E Ohio

Nature of Work: BROKEN W.M.

Company Name, Address, Phone No.: DWM 3900 S Ashland 312-747-1587

General / Prime Contractor Name, Address, Phone No.: SAME AS ABOVE

Include subcontractor information if applicable) SET

Safety Officer / Phone No. GLENN HUBER (815) 485-6161

Radiation Contractor / Phone No. (if applicable) STAR A. HUBER CONSULTANTS, INC.

Check if City Department Work ☒ Department Name: DWM

CDOT Permit No.: 153060 825

Today's Date: 1-30-14
2-1-14

Expected Start Date: 1-30-14

CDPH Approval / Date 2PM
[Signature] 2.4.13

Please return this completed form to the Chicago Department of Transportation, Division of Infrastructure Management, Public Way Permit Office, City Hall - Room 905, 121 N. LaSalle St., Chicago, Illinois 60602 during normal business hours (8:30 AM - 4:30 PM, Monday through Friday)

For CDPH Use Only

NOTE: RAD MONITORING CONDUCTED BY HUBER & ASSOCIATES ON BOTH
1.30.14 AND 2.1.14. NO RATES IDENTIFIED OVER ALLOWABLE
LIMITS.

333 SOUTH STATE STREET, ROOM 200, CHICAGO, ILLINOIS 60604

**Type: Broken Water Main (DWM Use Only), 400 E OHIO ST,
NL01**

Work order #: 14-00145132, Start Date: 01/31/2014

Status: In Progress

CSR Ticket # 14-00145132
Priority 1
Assigned Truck WD1303
Digger #
Water Atlas Page # 256B
Ward # 42

Location CDNE
Dept./Fund WATER
Investigated by
Notes:

Type Emergency Work
Permit # 453060825
Permit Exp. Date 3/1/14
Supervisor
Crew Foreman
Schedule Start 1/31/14
Date
Schedule End 1/30/14
Date
Activity W803 (601) (706) (803) circle one

Details:: WD1217 C. DRIVER ON SITE BROKEN WATER MAIN IN STREET CONFIRMED
EMERGENCY DO NOW SPOKE TO LINDA/DIGGER@9:12 PM D.N. 453021784 Created By:
71828652 Updated By: 5513
Purpose: REPAIRING BROKEN WATER MAIN IN STREET
Investigator: C. DRIVER
CDOT Comments: EMERGENCY DO NOW SPOKE TO LINDA/DIGGER@ 9:12PM D.N. 453021784
CDOT Lane: Curb and Traffic Lane
CDOT Side: S

Break/Leak Repair Not Reqd

User Entered Comments: Claude Driver 1-30-14: arrived on job site and found leak in the street flooding area. after shutting water main dwn and waiting for utility marks. excavated down to main and found branch of 12" tee open with connection missing, plugged tee turned main back up and found tee was part of side connection where 12" elbow and leg of pipe have blown away, continued excavating to expose area. showing large com ed duct on top of connection where as reconnecting may be in issue. plated hole and opened street back up for traffic, refer to district for further investigation.

Break/Leak Repair Not Reqd

User Entered Comments: Don Peterson 1-30-14: ohio and mcclurg ct. - complete a 4 valve intersection shut down at ohio & mcclurg ct. check valves beyond shut down.

(Mario Diaz for Com Ed.)

Break/Leak Repair Not Reqd

User Entered Comments: Robert Murdach: vactor truck wd1004 leave yard at 3:30, 3:52pm to 5:20pm
248 s clinton
6:45pm to 7:55pm 410 w ohio dump 8:32pm to 9:30pm

vactor truck wd1001 4:00pm mcclurg & ohio 7:30pm

Comments:

Required Information and Signatures

Completed: ☐ Yes ☐ No Turned Over to Next Crew: ☐ Yes ☐ No

Restoration Needed: ☐ Yes ☐ No Vendor Restore Needed: ☐ Yes ☐ No

Crew Foreman Sign.:

Asst. Superint. Sign.: